SPE RESPONSE FOR CERTIFICATE OF CORRECTION			
DATE : 9-9-04	Paper No.: 9 - 9-		
TO SPE OF : ART UNIT 285			
A response is requested with respect to the accompanying request for a certificate of correction. Please complete this form and return with file, within 7 days to: Certificates of Correction Branch - PK 3-915 Palm location 7580 - Tel. No. 305-8309 With respect to the change(s) requested, correcting Office and/or Applicant's errors, should the patent read as shown in the certificate of correction? No new matter should be introduced, nor should the scope or meaning of the claims be changed. Please see COC datect July 7, 2004 in the table of contents in			
		Thank You For Your Assistance	Certificates of Correction Branch
		The request for issuing the above-ide Note your decision on the appropriate box.	ntified correction(s) is hereby:
		Approved	All changes apply.
☐ Approved in Part	Specify below which changes do not apply.		
□ Approved in Part□ Denied	Specify below which changes do not apply. State the reasons for denial below.		
• •			
☐ Denied			

Clan G. Matheus SPE

2851 **Art Unit** Staple Here Only!

PRINTER'S TRIM LINE

Approved AM 9.9.04

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,714,277 B2

DATED : March 30, 2004

INVENTOR(S): Shinichi HARA et al.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 53, "On" should read -- At --. Line 55, "On" should read -- At --.

COLUMN 2:

Line 13, "a vessel which airtightly" should read -- an airtight vessel which --.

COLUMN 18:

Lines 25-30 should be deleted.

Line 62, "influence" should read -- influences --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,714,277 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82) No. of add'l. copies @ 30¢ per page



Staple Here Only!

PRINTER'S TRIM LINE

Approved AM 9-9-04

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.: 6,714,277 B2

DATED : March 30, 2004

INVENTOR(S) Shinichi HARA et al.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 37, "vender" should read -- vendor --.
Line 40, "vender," should read -- vendor, --.

COLUMN 24:

Line 25, "camber" should read -- chamber --.

Line 46, "whererin" should read -- wherein --.

Line 67, "displacement," should read -- displacement, and --.

COLUMN 25:

Line 16, "via movable" should read -- via a movable --.

Line 21, "said" should read -- wherein said --.

Line 25, "wherein" should read -- wherein the --.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,714,277 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page



PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.: 6,714,277 B2

DATED

: March 30, 2004

INVENTOR(S) Shinichi HARA et al.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

9-9-04

COLUMN 26:

Line 12, "manufactoring" should read -- manufacturing --.

Line 37, manufactoring" should read -- manufacturing --. Line 41, the second occurrence of "in order" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,714,277 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile FORM PTO 1050 (REV. 3.82)

No. of add'l. copies @ 30¢ per page